NYDE
nyde.co.uk

CHECKLIST

Uneven wall painting checklist

- [ ] Fill and sand all cracks and holes before starting
- [ ] Apply a mist coat to bare or heavily patched areas
- [ ] Choose matt or eggshell finish in a mid-tone colour
- [ ] Apply two thin coats rather than one thick coat
- [ ] Arrange lighting from multiple angles
- [ ] Allow each coat to dry fully before applying the next
- [ ] Cut in edges with a brush before rolling main areas